


SOME NOTES/ REMARKS

- Do not tighten the brushes 1848028 too tight with screws 3640550
- Re- grease the gearbox every 50 hours with 2 shots



Maredo BV
 Partspage GT250 REV 040